CY-FE

Schroeder Industries threaded strainers in Cast

Iron feature a machined seat which ensures a perfect fit for the removable, stainless steel screen. All sizes come complete with NPT blow-off with plug, which can be replaced with a ball valve for on-line blow-down of particulates.



Operating Pressures and Temperatures				
Туре	Size	psi @ Temp WOG		
FE 250	1/2"-3"	400 @ 150°F		

Standard Screens				
Size	Standard	Opening		
1/2"-2"	20 mesh	0.032"		
2 1/2-3"	3/64" perf	0.045"		

DIMENSIONS (Inches)					
Size (in)	A	В	Blow-Off NPT	Shipping Weight (lbs)	
1/2	3-3/16	2-1/16	3/8	5	
3/4	3-3/4	2-7/16	1/2	6	
1	4	2-5/8	1/2	8	
1-1/4	5	3-3/8	3/4	13	
1-1/2	5-3/4	3-7/8	3/4	15	
2	7	4-3/4	1	24	
2-1/2	9-1/4	5-7/8	1-1/2	37	
3	10	6	1-1/2	48	

*Dimensions and Weights are for reference only. Please contact Schroeder Industries for certified drawings.

Cast Y Strainer - Threaded - Socket Weld

How to Build a Valid Model Number for a Schroeder "Y" Strainer:

SP-CY		T				
Style	Material	Connection	Connection	Connection	Mesh	Code

^{**}Starting from the left to the right you will choose your Style and work your way through each category as illustrated above.

Style	Material		Connect	ion	Connection Size (Inches)		
SP-CY = Cast Y Strainer	_	mended for	☐ T = Threaded		☐ 1/4" ☐ 3/8" ☐ 1/2" ☐ 3/4"	☐ 1" ☐ 1-1/4" ☐ 1-1/2" ☐ 2"	☐ 2-1/2" ☐ 3"
Connection Class	·		·		Mark	Codo	
Threaded	FE	E2	В	Z	Mesh	Code	
☐ 1/4" ☐ 3/8" ☐ 1/2" ☐ 3/4" ☐ 1" ☐ 1-1/4" ☐ 1-1/2" ☐ 2" ☐ 2-1/2" ☐ 3"	250 250 250 250 250 250 250 250 250 250	- 600 600 600 600 600 600 600	1: 1: 1: 1: 1: 1:	50/300 50/300 50/300 50/300 50/300 50/300 50/300 50/300 50/300 50/300	☐ 4-100	☐ Omit = No☐ U = U/UM (whichever	•